

Operational Liaison Meeting FBW aircraft

Protections against fuel vapor ignition



Protections Against Fuel Vapor Ignition

Contents

- **Introduction**
- **Design Review**
- **In Service Aircraft Intensive Inspection**
- **General Conclusion**



Protections Against Fuel Vapor Ignition

Contents

→ Introduction

- Design Review
- In Service Aircraft Intensive Inspection
- General Conclusion



Introduction

- Flight TWA 800
- 17th July 1996
- Boeing 747-100
- Exploded in flight shortly after takeoff
- Reason:
 - Center tank explosion
 - Source of ignition not identified



Introduction

- Combination of several factors:
 - Low fuel level in center tank
 - Existence of flammable fuel vapor
 - Center tank elevated temperature
 - Most likely ignition source: excessive voltage, following a short circuit, entering the center tank
- Higher probability of occurrence on ground due to higher temperature



Introduction

Industry reaction

■ Industry formulated the Aircraft Fuel System Safety Program (AFSSP)


➤ Manufacturers

- Airbus
- Boeing
- British Aerospace
- Bombardier
- Fokker
- Lockheed

➤ Airlines Associations

- ATA
- AEA
- AAPA

➤ Airworthiness Authorities



Protections Against Fuel Vapor Ignition

Contents

- Introduction

- ➔ **Design Review**

- In Service Aircraft Intensive Inspection

- General Conclusion



Design Review

- Review of the possible reasons of the explosion
 - Flammable fuel vapor
 - Elevated temperature in center tank
 - Spark generation



Design Review

■ Flammable fuel vapor

- Explosion can only occur if flammable fuel vapor is present
- A spark generation has no effect on liquid fuel (no oxygen)
- Reduced risk of explosion in tanks as long as tanks are full:
 - Less quantity of oxygen
 - Lower temperature
- Heat is a contributing factor to increase flammability of fuel vapor

Design Review

■ Elevated temperature in fuel tank

➤ Fuel tank heated via:


- Outside ambient temperature
- Adjacent systems:
 - Air conditioning
 - Bleed air
 - Hydraulics



Design Review

Environment of the center tank

Example of the A320



Design Review

- Fuel and adjacent systems protected against overheating:
 - Fuel pumps protected against overheating (thermal fuses) and explosion (fuel pumps are located inside explosion proof canisters)
 - Air conditioning:
 - Thermal protection between center tank and air conditioning bay
 - Hot air ducts are fully insulated
 - Cockpit warnings in case of Pack or Duct overheating



Design Review

- Bleed air:
 - bleed ducts **fully insulated**
 - the system is continuously monitored to detect any ambient overheat in the vicinity of the hot air ducts
 - this particularly applies to wing and center section of fuselage
 - this triggers **cockpit warnings** and automatic bleed valve closure
- Hydraulic systems:
 - not considered as a heat contributor
 - » it is located in the landing gear bay (open area) and
 - » operating temperatures are lower than 100°C



Design Review

■ Spark protection


➤ fuel system:

- Pumps located inside **explosion proof** canisters
- No power cables inside the fuel tanks
- Fuel valve actuators are mounted externally to the fuel tanks
- Valve actuator casings are fully sealed and explosion proof
- Electrical (solenoid) valves **protected** against **electrical arcing**



Design Review

Fuel pump - explosion proof canister



Design Review

➤ Electrical system

- All structures are protected against lightning strikes and static electricity through electrical bonding (wires directly connected to the fuselage) to avoid accumulation of electricity
- Protection of all wires against short circuit and induced electrical fields
- Automatic tripping of circuit breaker to electrically isolate a failed system
- A320 FCOM recommendation (FCOM 3.04.24):

– On the ground, do not re-engage any fuel tank pump circuit breaker



Design Review

Bonding Lead (damaged)



Design Review

Conclusion

- Review confirmed the safe aircraft design in terms of ignition sources and overheat protection, even considering system failure.



Protections Against Fuel Vapor Ignition

Contents

- Introduction
- Design Review

→ In Service Aircraft Intensive Inspection

- General Conclusion



In Service Aircraft Intensive Inspection

- Inspection performed on all airbus aircraft types following requests of AFSSP
- More than 130 airbus in service aircraft inspected
- Fuel tank and electrical bonding intensive inspection:
 - Robust design confirmed, good condition, no unacceptable degradation with age



In Service Aircraft Intensive Inspection

- Electrical wires and connectors:
 - Good condition and performing intended function
- In some cases, improvements of maintenance training and procedures



Protections Against Fuel Vapor Ignition

Contents

- Introduction
- Design Review
- In Service Aircraft Intensive Inspection

→ **General Conclusion**



General Conclusion

- Intensive design review and in service aircraft inspection confirmed
 - The **safe original design** and
 - **No impact on safety** of forecasted minor material degradation with age
- Airbus will continue to actively participate to safety programs to further improve quality and safety of its aircraft





Thank you for your attention

